

## 사 진 자 료



<양동마을 수졸당 벽체 균열>



<양동마을 송침종택 담장기와 탈락>



<청하향교 담장 기와 탈락>



<청하향교 벽체탈락>